

GOVERNMENT OF ANDHRA PRADESH
STATE DISASTER RESPONSE & FIRE SERVICES DEPARTMENT

From:
The Director General,
State Disaster Response & Fire Services,
Vijayawada .

To:
The Secretary & Correspondent,
Deekshitha Educational Development Society,
Sy.No's: **313/211 ,6A**
Oguru (V)Kandukur(M),SPSR Nellore District.

Re.No.98/NSB/NLR/2015, Dated:28-06-2025

Sub : Andhra Pradesh Disaster response & Fire services Department – Southern Region – SPSR Nellore District – Issuer of No Objection Certificate for occupancy to the Existing Educational Building of **Deekshitha Educational Development society, SY.No's. 313/211 ,6A, At Oguru Village,Kandukur (M), SPSR Nellore District-Regarding.**

Ref: 1. Letter from the Secretary and Correspondent of Deekshitha Educational Development Society ,Sy.No's. **313/211 ,6A.** At Oguru Village,Kandukur (M), SPSRR Nellore District.
2. Rc.No.2305/B2/2025, Dt. 23-06-2025 of the Director General of State Disaster Response and Fire Services Department.

--:--

In obedience to the recence 1" cited above, the Director of **Deekshitha Educational Development Society, S.Y.No's: 313/211 ,6A.. At Oguru Village,Kandukur, SPSR Nellore District.,** has applied for No Objection Certificate.

2. Vide reference 2nd cited, I have Inspected the above Educational Building on 26-06-2025 and recommended the No Objection Certificate at the Educational Building is not changed or altered from the date of Building completion and provided required Fire Safety Measures per furnished below.

3) i) Particulars of the Building:

a)	Address of the Building	Deekshitha Educational Development Society, S.Y.No's. 313/211,6A, Oguru (V)Kandukur(M),SPSR Nellore District.
b)	Area of plot Height of the building	7608.09 sqmts/ 33.4 Sq.Fts
c)	No. of blocks/floors	03 No's./{(Ground +1st and 2nd Floor .)}

ii) Open Spaces:

Side	Open Space required as per NBC	Open space provided	Deficit/Remarks
Nort	06.00 Mtrs.,	06.00 Mtrs.	Nil
East	06.00 Mtrs.	48.66 Mtrs,	Nil
South	06.00 Mtrs.	06.00 Mtrs,	Nil
west	06.00 Mtrs.	06.00 Mtrs.,	Nil

iii) Floor wise particular

Sl.No.	Floor	Area in sq. Mts.	Occupancy	Occupant Load Declare By management
1.	Ground	1295.58	Educational	200
2.	First	1295.58	Educational	200
3.	Second	476.96	Educational	200
	Total:	3068.12	--	600

iv) Means of Escape(a):

Sl.No.	No. of Staircases	Widt in Meter	Total Width
1.	Internal Staircase – 03 Nos.	3.66+3.66+3.66Mtrs	10.988 Mtrs.
	Total: 3 Nos	10.98 Mtrs	

b)

Highest No. of Students In a Floor	Width of Staircases required(No. of Students divided by 50=-----mts.	Aggregate Width of Staircases provided	Deficit
200	200/50=04.00Mtrs.,	04.00Mtrs	Nil

C) Fire Safety Measures:

Sl.No.	Fire Sfty Measures	Required as per Table 23 of NBC of India 2005	Provided	Deficiency
1.	Fire Extinguishers	28 Nos.	28 Nos.	Nil
2.	Fire Buckets	32 Nos.	32 Nos.	Nil
3.	Hose Reel	05.Nos.	05.Nos.	Nil
4.	Automatic Sprinkler System in Basement if area of basement exceeds 200sq. Meters.	Not required	Not required	NR
5.	a) terrace Tank capacity 10,000 litres. b) Additional 5000 litres if area of basement exceeds 200sq. Meters	10,000 Ltrs.	10,000 Ltrs.	Nil
6.	a) One Booster pump of 450 LPM. b) One Booster pump of 900 LPM if Basement area exceeding 200 M2	1 No. 450 LPM	1 No. 450 LPM	Nil

4. The Fire Safety systems were tested by me, during the inspection and performance found satisfactory. Hence, it is issued No Objection Certificate for Occupancy to the existing Educational Building at of Deekshitha Educational Development Society, S.Y.No's **313/211 ,6A.**, At Oguru (V), Kandukur Mandal, SPSR Nellore District. subject to the following conditions.

i.	All the Fire Protection arrangements shall be maintained in good repair as seen during inspection.
ii.	All the escape/exit routes shall not be kept locked / blocked or encroached.
iii.	All the occupants must know the correct method of operation of the fire fighting system installed.
iv.	Any loss of life or property due to non-functioning of fire safety measures and other installations shall be the responsibility of the management.
v.	All students / staff members of the institution shall be trained to operate the fire safety equipments during emergency.
vi.	Addition/alteration, if any in the building may be obtained with prior permission from this department
vii.	Mock drills should be conducted once in 3 months for initial two years. Thereafter, once in every 6 months.

5) The Management should maintain all Fire Safety Measures in good condition during renewal period.

6) The Management paid Online challan No.14568, Dated 20-06-2025 for Rs. 134,000/- , towards Charges for the year 2025 . Hence the No Objection Certificate issued to Deekshitha Educational Development Society, S.y.No's **313/211 ,6A.**At Oguru(V)Kandukur (M), SPSR Nellore District. in terms of this No Objection Certificate valid up to 27-06-2026.


Director General

StateDisaster Response and Fire Services
Andhrapradesh,Vijayawada.

Copy to the Secretary & Correspondent **Deekshitha Educational Development Society, S.Y.No's. 313/211 ,6A, At Oguru(V), Kandukur(M),SPSR Nellore District..**

Copy Submitted to the District Fire Officer, Nellore for favour of kind information.

Copy to the District Disaster Response & Fire officer,SPSR Nellore District